# Interim Investigation Report pertaining to the serious marine casualty 241/18

Grounding of the Tank Motor Vessel PAZIFIK off Indonesia on 9 July 2018

5 July 2019





Pursuant to the second sentence of Article 28(1) of the Law to improve safety of shipping by investigating marine casualties and other incidents (Maritime Safety Investigation Act – SUG) in conjunction with Article 14(2) of Directive 2009/18/EC of the European Parliament and of the Council of 23 April 2009 establishing the fundamental principles governing the investigation of accidents in the maritime transport sector, the Federal Bureau of Maritime Casualty Investigation publishes an interim report within a period of 12 months of a very serious or serious marine casualty if it is not possible to complete the corresponding investigation report within that period.

This interim report should not be used in court proceedings or proceedings of the Maritime Board. Reference is made to Article 34(4) SUG.

The German text shall prevail in the interpretation of this interim report.

Issued by:
Bundesstelle für Seeunfalluntersuchung – BSU
(Federal Bureau of Maritime Casualty Investigation)
Bernhard-Nocht-Str. 78
20359 Hamburg
Germany



Director: Ulf Kaspera Phone: +49 40 3190 8300 posteingang-bsu@bsh.de

www.bsu-bund.de

Fax: +49 40 3190 8340

\_\_\_\_\_



### 1 FACTUAL INFORMATION

#### 1.1 Photograph of the ship



Figure 1: Photograph of the PAZIFIK

#### 1.2 Ship particulars

Name of ship: PAZIFIK

Type of ship: Liquefied gas tanker

Nationality/Flag: Germany
Port of registry: Rostock
IMO number 9293430
Call sign: DBIP

Owner (acc.to Equasis) MS "PolarPacific" GmbH & Co. KG

Operator: F. Laeisz Year built: 2005

Shipyard/Yard number: Hyunday Heavy Ind. Korea

Classification society:

Length overall:

Breadth overall:

Draught (max):

Gross tonnage:

Deadweight:

Engine rating:

DNV GL

204.98 m

32.23

20.80

42937

11300 kW

Main engine: Hyunday-MAN/B&W 5S60MC-C

(Service) speed 15,2 kts Hull material: Steel

Shell plating construction: Double bottom

Minimum safe manning: 21



## 1.3 Voyage particulars

Port of departure:: Luwuk, Indonesia Port of call: Kwinana, Australia

Type of voyage: Merchant shipping/international Cargo information: Dangerous goods, liquefied gas

Manning: 21

Draught at time of accident: Forward: 8.0 m, aft 9.0 m

Pilot on board: No Canal helmsman: No Number of passengers: None

## 1.4 Marine casualty or incident information

Type of marine casualty: Serious casualty, grounding Date, time: 09/07/2018 1110 Local time

Location: Between the islands of Komodo and Banta

Latitude/Longitude:  $\phi$  08°29,21'S  $\lambda$  119°20,31' E


Ship operation and voyage

Segment: Open sea Place on board: Ship's bottom

Consequences: Grounding on a reef, unseaworthy due to

damage of the ship's bottom

Extract from Navigational Chart: Paulau Jailamu to Pulau Serbete, BA 2910





Ref.: 52/18 Federal Bureau of Maritime Casualty Investigation

## 1.5 Shore authority involvement and emergency response

Agencies involved: BSU

Resources used: Tug on stand-bye

Actions taken: Transferring of ballast water and cargo

Results achieved: Ship manoeuvred clear



#### 2 SUMMARY

At about 1110 local time on 9 July 2018, the German tank motor vessel PAZIFIK grounded on a shoal between the islands of *Komodo* and *Banta* on  $\phi$  08°29,21'S  $\lambda$  119°20,31' E. The ship carried a cargo of 18,000 t ammonia. No cargo spilled since only the forepeak and ballast water tanks were damaged. At about 0850 local time on 11 July 2018 the PAZIFIK manoeuvred clear of the shoal by transferring cargo and ballast water and sailed to a repair yard in Singapore by her own power.

Approx. 50 m of the double bottom were renewed during the repair work and the rudder, which was damaged during the towing attempt, was repaired.




Shoal on port side and starboard side with rocks on the water surface



Damaged forepeak and ballast water tanks

Ref.: 52/18

On the day of the accident, the ship was navigated by a Transas Navilailor 4000 ECDIS and the ENC-nautical chart id 300295 ed.3.1 S-67. The shallow was not plotted in this nautical chart.



Scene of the accident on the electronic chart (on board)

On 9 July 2019, the ship's owner promptly notified the Federal Bureau of Maritime Casualty Investigation (BSU) of the accident and the BSU started the investigation immediately. A simulation at the Federal Maritime and Hydrographic Agency reconstructed the course of the ship. This confirmed that the shoal was not plotted. The BSU investigations focus on this issue. Meanwhile, the BSU has largely concluded the investigations.

Since the time limit of one year set by the European Union and implemented into national law by the Federal Republic of Germany, to publish an investigation report after a very serious or serious marine casualty has occurred, cannot be satisfied, the public is informed by issuing the aforementioned Interim Investigation Report.